

Receive Job - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes...

Address <http://alldb48.geps.ge.com/2038/tops3/topsReceive.jsp>

Links [Inspection1\[1\].gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Holmat](#) [Free Visio](#) [Free Yahoo](#) [Google](#)

**TOPPS<sup>3</sup>**

[Home](#)[T&RS Home](#)[Update Profile](#)[Operations](#)[Planning](#)[Reports](#)[Reference](#)

EHS  
Quality  
PAC  
DART  
Gen. COE  
ST COE

## Inspection and Repair Services

### Receive Job

Quantity  S/N Prefix  Dwg#  \* Optional

Select the Job# :

Job#	Customer	Description
31298	GENERAL ELECTRIC	(14) F/9E FUEL NOZ

OR

Select the Temporary Job# :

Job#	Customer	Description
------	----------	-------------

OR

If Job# is not Available :

New Temp Job#

Receive Parts - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Stop Refresh Home Search Favorites History Mail Print Edit

Address <http://alldb48.geps.ge.com/2038/tops3/topsReceiveFinish.jsp>

Links [Inspection\[1\].gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Hotmail](#) [Free Yahoo](#) [Free Visio](#) [Free Yahoo](#) [Google](#)

Yahool Mes Go

[Home](#)
[TOPS Home](#)
[Update Profile](#)
[Operations](#)
[Planning](#)
[Reports](#)
[Reference](#)

EHS  
Quality  
PAC  
DART  
Gen. COE  
ST COE

## Inspection and Repair Services

### Receive Parts

Job# 31298  
Customer GENERAL ELECTRIC

Description (14) F9E FUEL NOZ  
Segment PG,GAS

	Drawing #	Serial #	Tag #
1	2077	AWER456	2345
2	2077	ASER	5678
3	2077	ASDR	6789
4	2077	292	6735
5	103E3026P001	AE	
6	103E3026P001	AE	
7	103E3026P001	AE	
8	103E3026P001	AE	
9	103E3026P001	AE	
10	103E3026P001	AE	

Add Part [L304](#)
Attach File [L305](#)
Temp Save [L306](#)



TOPS 3.0 EEE0560

520

Office

Microsoft

Home Page - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History Favorites

Address http://adlba48.geips.ge.com:2038/tops3/topsFirst.jsp

TOPS<sup>3</sup>

Home

IGRS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART

Gen. COE

ST COE

Inspection and Repair Services

Welcome :

Site :

Planning

Reports

Approval

502

504

503

22 Hierarchical Menu Trees Created

Start

Inbox - Microso...

Microsoft Powe...

FW: Test Script...

ap

Internet

11:24 AM

Fig 5

Planning - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History Favorites

Address http://alldba48.geps.ge.com:2038/tops3/topsPlanning.jsp

Office

Microsoft

TOPS<sup>3</sup>

Home I&RS Home Update Profile Operations Planning Reports

EHS Quality PAC DART Gap COE ST COE

Inspection and Repair Services

Planning Search

Select the Available Job#

Job# 30481 | TRANSCO | F3LP ROTOR

Customer Description

Segment Component Customer Drawing #

Narrow Search

Plan Information

Standard Plan SP20001 | 7E11 Rotor

OR

Previously Built Plan

Next Cancel

Start

22 Hierarchical Menu Trees Created

Inbox - Mic... Planning - ... Microsoft P... FW: Test S... zip

Internet

11:54 AM

Fig 6

7001

Planning Parts - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History

Address http://aldiba48.geps.ge.com:2038/tops3/topsPlanningParts.jsp

Office

Microsoft

7001

702

703

706

TOPS<sup>3</sup>

Home

ISRS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART

Gen. COE

ST COE

Inspection and Repair Services

Planning Assembly

Assembly description

Job# 30481 Plan 30481-SP20001

Segment PG,GAS Customer TRANSCO

Drawing # Serial # Component

Part Description

Attach >>

Detach >>

Available 705

Selected

SubPlan Description

SubPlan Description

Next Cancel

Parts Structure

2077-30481

2077-AS12345

2077-AS12346

2077-AS12347

22 Hierarchical Menu Trees Created

Start

Inbox - Mic...

Planning P...

Microsoft P...

FW: Test S...

2p

Internet

11:57 AM

F.87





TOPOT20" EZE0660

900

Approve Plan - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History

Address http://alidba48.geips.ge.com:2038/tops3/topsApprove.jsp

Office

Microsoft

TOPS<sup>3</sup>

Home

LARS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART

Gen. EOE

ST EOE

Inspection and Repair Services

Approve

901

Plan for review

Method Sheet

Load

Approve

Inspection Form

Cancel

Start

Inbox - Mic...

Approve P...

Microsoft P...

FW: Test S...

zip

Internet

11:59 AM

Fig 9

TOPP2000E000000

1000

Approve Planning Parts - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History

Address http://atldb48.geps.ge.com:2038/tops3/topsApprovePlan.jsp

Office

Microsoft

TOPS<sup>3</sup>

Home I&RS Home Update Profile Operations Planning Reports Reference

EHS Quality PAC DART Gen. COE ST COE

22 Hierarchical Menu Trees Created

Approve Plan Steps

List of steps Plan T00001-SP00005 RO # T00001 Part Type Bucket Created for : Drawing #

1001

NO SUBPLANS ARE ATTACHED

1002

1003

Options Reason for decline!

Accept Decline

Finish

Start

Inbox - Mic...

Approve Pla...

Microsoft P...

FW: Test S...

zip

Internet

12:01 PM

Fig 10

811

Process Steps - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes.

Address <http://atldb48.geps.ge.com/2038/tops3/tops/ProcessJob.jsp>

Links Inspection1[1].gif IM Quality Procedures Manual GE Quality Manual Free Holmail Free Yahoo Free Visio Free Yahoo Edit Google

Go

TOPS<sup>3</sup>

Home

1&RS Home

Update Profile

Operations

Reference

EHS  
Quality

## Inspection and Repair Services

### Process Job

Job# 31898 Plan 31898-SP00002  
Customer GENERAL ELECTRIC Component Rotor

Check job status details Show Parts Status ~1203

#### Select step to proceed with

Sub Plan	Step	OpCode	Duration	Description	Select
1	010	BA01		Receive Buckets Issue receiving report	<input type="checkbox"/>
1	020	BZ01		QC TOLLGATE *	<input type="checkbox"/>
1	030			TECH TO REVIEW DATA AND ADVISE NEXT OPERATION	<input type="checkbox"/>
1	040	BA02		Issue incoming visual inspection report	<input type="checkbox"/>
1	050	BA05		Clean buckets	<input type="checkbox"/>
1	060	BA07		Issue incoming FPI report	<input type="checkbox"/>
1	070	BA10		Dimensionally inspect bucket	<input type="checkbox"/>

Back Next Close

Fig 12

1201

1202

1204

TOPICS EEE060

1300

Process - Parts Status - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes

Address <http://altdba48.geps.ge.com/2038/tops3/topsShowProcessPartStatus.jsp>

Links [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Free Hotmail](#) [Free Yahoo](#) [Free Yislo](#) [Free Yahoo](#) [Google](#)

# TOPS<sup>3</sup>

- Home
- 1&RS Home
- Update Profile
- Operations
- Reference
- EHS Quality

## Inspection and Repair Services

### Process - Parts Status

Sub Plan Step Drawing# Serial# Tag# Hold State

1	010	2077-TYR4356	ServiceRunning
---	-----	--------------	----------------

[Back](#)

F1813

Address <http://atldb48.geps.ge.com/2038/tops3/topsProcessExecution.jsp>

Links [Inspection111.gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Hotmail](#) [Free Yahoo](#) [Free Visto](#) [Free Yahoo](#) [Google](#)

Back Stop Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes

## Process Job

RO #: 31898 ~ 1402

Customer: GENERAL ELECTRIC

Sub Plan: 1 Step: 010

Drawing: 2077

Component: Rotor

Op.Code: BAD1 Description: Receive Buckets.  
Issue receiving

Select any of the following:

Fill Inspection Form

Add Additional Form

Attach File View File

Job Log

View Update

Available Parts

Work Complete >>

<< Undo Complete

Select All

Parts Hold

Voucher

Hours

Complete Parts

< Back Finish Cancel

## QPL FA05

EXTERNAL INSPECTION SEE QPS RA05

CUSTOMER

EXTERNAL FIRE DAMAGE.

JOE NO:

YES NO

**IF DAMAGE IS INDICATED IN CHECKS MAKE A NOTE BELOW DESCRIBING**

## TANK WALL DISTORTION

## WELD CRACKING

HV SIDE Y ☉ N LV SIDE Y ☉ N HV SIDE Y ☉ N LV SIDE Y ☉ N

1503

COVER DAMAGE

CONTROL CABINET DAMAGE

[illegible]

## ACCESSORY DAMAGE

## SAMPLE PLUMPS

YOUNG, C. C. THERMAL DEV.

CONFIDENTIAL

CNY

## PUMPS & VALVES

CT OUTLET

## COOLING PIPING

٢٠٠

## FANS

EUSH, ADPTRS

## RADIATORS

YOUNG

REMARKS

INSPECTED BY:

AUDITED BY:

DATE \_\_\_\_\_

# h-u




Fig 16






Fig 17




Fig 18




Fig 19




Fig 20




Fig 21